

**RAPPAHANNOCK ELECTRIC COOPERATIVE
Fredericksburg, VA**

**OUTDOOR LIGHTING SERVICE – NT
SCHEDULE OLN**

I. AVAILABILITY

Available in the territory acquired by the Cooperative in Case No. PUE-2009-00101, subject to the Terms and Conditions of the Cooperative on file with the Virginia State Corporate Commission.

II. APPLICABILITY

Applicable for lighting service sold for outdoor lighting supplied from the existing overhead secondary and contracted for by a private Customer. The rating of lamps in lumens is for identification and shall approximate the manufacturer's standard rating.

III. MONTHLY RATE

A. Distribution Delivery Charges:

Monthly Distribution:

<u>Type of Fixture</u>	<u>Delivery Charge</u>
100 Watt High Pressure Sodium (HPS)	\$ 8.12
200 Watt High Pressure Sodium (HPS)	\$ 14.07
175 Watt Mercury Vapor (MV)	\$ 8.16
400 Watt Mercury Vapor (MV)	\$ 15.01

B. Electricity Supply Service Charges:

<u>Type of Fixture</u>	<u>Lumen</u>	<u>kWh/Month</u>	<u>Monthly Charge</u>
100 Watt HPS	9,500 Lumen ¹	51 kWh	\$ 1.06
200 Watt HPS	22,000 Lumen ²	86 kWh	\$ 1.81
175 Watt MV	8,150 Lumen ¹	74 kWh	\$ 1.57
400 Watt MV	21,500 Lumen ²	162 kWh	\$ 3.42

¹Cooperative will provide lamp, photo-electric relay control equipment, fixture, and upsweep arm not over four (4) feet in length, and will mount same on an existing pole carrying secondary circuits.

²Cooperative will provide lamp, photo-electric relay control equipment, fixture, and upsweep arm not over six (6) feet in length, and will mount same on an existing pole carrying secondary circuits.

When facilities, in addition to those specified previously are required to provide outdoor lighting service, the Customer will pay in advance the cost of installing all

B. Electricity Supply Service Charges (continued)

additional facilities. For the Cooperative's facilities installed prior to December 13, 1985, the monthly rental charges will continue as follows:

1. \$2.74 for each standard distribution wood pole required,
2. \$0.013 per foot for each foot of span length of wires required, and
3. \$2.74 of each kilovolt-ampere of transformer capacity installed.

The Customer may elect to own and maintain poles and secondary circuits on his property to accommodate the installation of the outdoor lighting fixture. Such poles and circuits shall meet Cooperative specifications.

IV. LEVELIZED PURCHASED POWER FACTOR

All kilowatt-hours under this schedule will be adjusted as per Schedule LPPF through June 30, 2011.

V. WHOLESALE POWER COST ADJUSTMENT

All kilowatt-hours under this schedule will be adjusted as per Schedule WPCA-1-NT beginning July 1, 2011.

VI. TERM OF CONTRACT

Service is sold under contract to take continuous service under this rate schedule for a minimum period of three (3) years or longer for Distribution Delivery Charges.

In the event of early termination, the Customer shall pay either the balance of the contract responsibility or the net cost of installation and removal of the facilities installed by the Cooperative to serve the Customer, whichever is less.

VII. GENERAL

All Cooperative-owned facilities necessary for service under this schedule shall be maintained by the Cooperative and all such service and maintenance will be performed only during the Cooperative's regular scheduled working hours. The Cooperative shall be allowed two working days after notification by the Customer to replace all burned-out lamps.

All lamps are lighted from dusk to dawn every night, or for approximately 4,200 hours per annum.

The Customer shall obtain written approval from public authorities for lights to be located on public thoroughfares.

VII. GENERAL (CONT)

The Customer shall select the location of all poles installed on the Customer's property under the provisions of this schedule. Pole relocation or removal will be at the Customer's expense. All pole locations shall conform to all safety standards, and state and municipal regulations. The Customer shall be responsible for all damages to, or loss of, the Cooperative's property located on the Customer's premises, unless resulting from causes beyond the Customer's control.